## WOOD COMBUSTION TABLE:

Fast flame		Quick flame	Strong heat	<b>Good Coal</b>
Alder	X	X		
Birch	X	X		X
Maple	X	X	X	X
Oak	X	X		
Evergreen	X	X	X	
Ash-tree	X	X		
Beech	X	X		X
Elm	X			
Willow	X	X		
Lime tree	X			
Wild cherry	X	X		X